

## Change Notification – White 1 Litre Dye/Stain Bottles

6 October 2011

Dear Customer,

As a result of problems with the moulding of our standard 1 litre white HDPE stain bottle, and associated leakage problems, the manufacturer has discontinued production of this bottle. An alternative bottle from the same supplier has been sourced, manufactured from the same HDPE material, using a new moulding. The new bottles are a different colour (natural rather than white) but are otherwise identical to the standard bottle you are used to.

Standard bottle: 1000ml HDPE Standard round ratchet neck: Product Code - CA0920WD3

New bottle: 1000ml HDPE Standard round ratchet neck: Product Code - CA0920ND0

Product codes affected by the bottle change are:

HS100	HS255	HS335	HS576
HS132	HS260	HS340	HS615
HS137	HS262	HS345	HS620
HS140	HS265	HS350	HS625
HS145	HS270	HS355	HS630
HS160	HS275	HS360	HS632
HS170	HS280	HS375	HS675
HS202	HS295	HS380	HS720
HS210	HS300	HS390	HS762
HS230	HS310	HS400	HS763
HS232	HS315	HS445	HS785
HS250	HS330	HS480	HS787

This change has been made at short notice, and is a temporary solution to the leakage problem. We are now looking to source a more suitable bottle/closure configuration for our stain products, and will notify you in good time as soon as we are in a position to introduce this further change.


 A handwritten signature in blue ink, appearing to read 'K Punter', is written over a light blue horizontal line.

Ken Punter  
Quality Assurance/Technical Manager

### TCS Biosciences Ltd

Botolph Claydon Buckingham

MK18 2LR United Kingdom

t +44 (0)1296 714222

f +44 (0)1296 714806

e sales@tcsgroup.co.uk

i www.tcsbiosciences.co.uk

